

VME64 Standard Clarification



- Issue - Board Components that conflict with guide rail
- Cause: No Max Dimension for Guide Rail
- RULE 7.13: Solder filets, tracking, and components on VMEbus boards **MUST NOT** be closer than 2.5 mm (0.098 inch) from the top and bottom edges of the board to guarantee clearance between them and the board guides. Figure 7-2 and Figure 7-3 show dimensions.

Guide Rail Issue

Cross section of guide rail

